SEP 2 6 2005 &


REPLACEMENT SHEET

Michael D. Mundt et al. Shee

AIR BEARING SLIDER HAVING...


Serial. No.: 10/608,700 S01...

Sheet 1 of 11 S01.12-0979



REPLACEMENT SHEET Michael D. Mundt et al. Sheet 2 AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700 S01.12-0

Sheet 2 of 11



REPLACEMENT SHEET

Michael D. Mundt et al. Sheet 3 of AIR BEARING SLIDER HAVING...

Serial. No.: 10/608,700 S01.12-09

Sheet 3 of 11





Fig. 3

REPLACEMENT SHEET Michael D. Mundt et al. AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700 S01.12-097

Sheet 4 of 11



Michael D. Mundt et al. AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700

Sheet 5 of 11 S01.12-0979





Fig. 5

REPLACEMENT SHEET Michael D. Mundt et al. Sheet AIR BEAMING SLIDER HAVING... Serial No.: 10/608,700 S01.1

Sheet 6 of 11




REPLACEMENT SHEET

Michael D. Mundt et al. Sheet 7

AIR BEARING SLIDER HAVING...

Serial. No.: 10/608,700 S01.12-09

Sheet 7 of 11








Fig. 8

Michael D. Mundt et al. AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700


Sheet 8 of 11





REPLACEMENT SHEET
Michael D. Mundt et al. Sheet
AIR BEARING SLIDER HAVING...
Serial. No.: 10/608,700 S01.1:

Sheet 9 of 11








Fig. 12

Michael D. Mundt et al. AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700 Sheet 10 of 11 S01.12-0979





Michael D. Mundt et al. AIR BEARING SLIDER HAVING... Serial. No.: 10/608,700

Sheet 11 of 11

